


Making Ethernet (CAT5) Cables

1. Cut cable to length.
2. Strip protective sheathing from around wires approximately 0.5 in from end.
3. Cut off nylon fiber.
4. Separate wires.
5. Place in this order (Left to Right):


1. White / Orange
2. Orange
3. White / Green
4. Blue
5. White / Blue
6. Green
7. White / Brown
8. Brown

6. Place in RJ-45 connector gold pins facing you.
7. Crimp with RJ-45 crimper.
8. Repeat on other end.

RJ-45 Connector



When placed head to head clip side down, they should be opposite.



GRN 01/21/02