

Pinout for Null Modem Serial Cable

Note: This is the type of cable that is needed for the slaving of a Printer off of the back of a TCS.

Cut and strip back the insulation shielding your Cat 5 strands (You should end up with eight multi-colored wires.)

1. Green-Green
2. Red-Orange
3. Orange-Red
4. Blue-Yellow
5. Yellow-Blue
6. Purple-Grey
7. Gray-Purple
8. Black-Black
9. Brown-Brown
10. Shielded Cable-Shielded Cable