

Logic Controls, Inc. PD 3000 Series Display Pole

1. Connect the DB9 connector to one of the terminal's serial ports.
2. Connect the DIN6 connector from the display pole to the DIN6 connector of the interface cable.
3. Connect the female phone jack of the power adapter to the male phone jack of the interface cable

GRN 02/06/02