


SYMBOL LS9100

WITH SERIAL CONNECTOR

SCAN SHEET

STI





STANDARD RS-232C



BAUD RATE 9600



NO PREAMBLE
(<DATA>)



DO NOT TRANSMIT
UPC-A CHECK DIGIT



PRIMARY SCANNER PORT



SEND ALL DATA THAT REMAINS

SCAN THE **SEND ENTER KEY**

ONCE FOR ONE CR

OR TWICE FOR TWO CR

