




[Home](#) [Site Map](#)  [RSS Si](#)

[PRODUCTS](#) [SUPPORT](#) [BUY ONLINE](#) [NEWS & INFO](#) [Find a Reseller](#) [For Partners](#) [About RSS](#) [Contact RSS](#) [seagate.com](#)



TAPE SUPPORT

FATAL ERROR CODE DEFINITION

[Tape Encyclopedia](#)

[Floppy Resources](#)

[Parallel Resources](#)

[Tape Accessories](#)

[Warranty and Repairs](#)

[Trouble-shooting](#)

[Diagnostic Utilities](#)

[Drivers](#)

[Firmware](#)

[Contact Tech Support](#)

Fatal Error Message Descriptions

Error Code	Description	Possible Causes
0	No Error	None - Normal operation
1	Timeout Occurred	Possible DMA and/or IRQ problem, or less frequently drive failure.
2	End of Media Detected	Normal condition at End of Media
3	Media Error	Possibly bad media, heads need to be cleaned, head alignment problem, da tape prematurely (operation not completed) ejected.
4	No Media Present	Normal condition. No tape in drive.
5	Filemark Detected	Normal condition. Two filemarks are always written at the end of every Bac
6	No more Data or unexpected End of Data	Normal condition when it is not followed by a red error box in the software. similiar to Error #3 above. Can be the result of a bad backup (typically caus failure during the backup, or premature tape ejection).
7	Invalid Drive Command	The drive was issued an invalid command. This problem should not occur.
8	Drive Reset	A drive reset has been detected. It is not normal for this error to occur duri like backup or restore. If it does occur, it is often an electrical noise related Check terminators, cables and controller card.
9	Write Protect Error	Attempted to write to a write protected cartridge.
10	Hardware Error	Drive failure. On a MaynStream 2200HS (8mm) could be media error.
11	Internal Driver Software error	Software problem
12	End of Physical Tape detected	Wrote over the end of the tape. Most likely cause is bad media.

[PRIVACY](#) [COPYRIGHT](#) [LEGAL](#)