

## **Spotline Error Message**

**Problem:** Ethernet Spotline reads "internal error 103 waiting for serial number

**Solution:** Replace Spotline, CMOS is blown/spotline is bad