




LS 6000 Scansheet



Start at the top of the page, scan each barcode, one at a time.




Set All Defaults




Combination Mode
(constant-on omnidirectional /
triggered single scan line)




No UPC-A check
digit



No Preamble




Scan Options




<data>
<suffix>

Scan the **SEND ENTER KEY**
code once to stop on the Qty field,
or twice to stop on the next line is
Point of Sale.



Send Enter Key



Done