


# **SYMBOL LS5000**


**WITH ATTACHED LT1700 HANDHELD**

**SCANNER**


**SCAN SHEET**




**ENABLE PROGRAMMING**




**SET ALL DEFAULTS**




**IBM PC/AT**




**DO NOT TRANSMIT UPC-A CHECK DIGIT**




**DO NOT TRANSMIT UPC-E CHECK DIGIT**



**NO PREAMBLE  
(<DATA>)**




**EITHER SCANNER PORT**



**SEND ALL DATA THAT REMAINS**

**SCAN THE SEND ENTER KEY**


ONCE FOR ONE CR  
OR TWICE FOR TWO CR



**SEND ENTER KEY**



**SAVE RULE**



**DISABLE PROGRAMMING**