

SYMBOL LS9100


WITH SERIAL WEDGE

SCAN SHEET


STI40-0200



SET ALL DEFAULTS



STANDARD RS-232C



BAUD RATE 19,200



SET SYNAPSE RS-232 DEFAULTS



ENABLE LS 9100 COMMUNICATION



19,200



RTS STATE HIGH



**FEMALE HOST CONNECTOR
MALE LOCAL CONNECTOR**



**TXD PIN 2 HOST
TXD PIN 3 LOCAL**



NO PREAMBLE
(<DATA>)



DO NOT TRANSMIT
UPC-A CHECK DIGIT



PRIMARY SCANNER PORT



SEND ALL DATA THAT REMAINS



SEND ENTER KEY



SAVE RULE