



SYMBOL M2000 CYCLONE




Symbol M2000 Scan sheet. For use on Serial or Ethernet terminals that use a standard keyboard connection.




SYMBOL M2000 CYCLONE



Set All Defaults



Set Synapse Pc Wedge Defaults



Do Not Transmit UPCA Check Digit

SYMBOL M2000 CYCLONE



No Preamble
(<DATA>)




Begin New Rule



UPCA

SYMBOL M2000 CYCLONE



**Send All Data
That Remains**



Send Enter Key



Send Enter Key



Save Rule