

## INSTALLING 2<sup>ND</sup> HARDDRIVE

8-27-01

### mkdev hd [enter]

Pick # 2 add scsi hard drive

host adapter [default] ad or alad blad

host adapter 0

bus 0

id 1 or id of drive

lun [default] 0

update scsi configuration yes

relink kernel at this time only if there are no more hd's to configure

to add another hd answer no and make mkdev hd again.

If finished answer yes .

Boot by default yes

Environment to be rebuilt yes

Reboot and start mkdev hd again

MKDEV HD [enter]

Pick # 2 add scsi hard drive

host adapter [default] ad or alad blad

host adapter 0

bus 0

id 1 or id of drive

lun [default] 0

Do you want to continue yes

2 use entire disk

q quit

l scan entire disk or q to quit

scan [quick/destructive]

do you wish to make manual adjustments [yes]

n for name

0 for division

name [work2]

q quit

i install

mkdev fs

l add filesystem

/dev/work2

work2

yes

[1] always mount

[yes] allow users

mountall