

INSTALLING 2ND HARDDRIVE

```
MKDEV HD [enter]
Pick # 2 add scsi hard drive
host adapter [default] ad or alad blad
host adapter 0
bus 0
id 1 or id of drive
lun [default] 0
update scsi configuration yes
relink kernel at this time only if there are no more hd's to configure
to add another hd answer no and make mkdev hd again.
If finished answer yes .
Boot by default yes
Environment to be rebuilt yes
Reboot and start mkdev hd again
MKDEV HD [enter]
Pick # 2 add scsi hard drive
host adapter [default] ad or alad blad
host adapter 0
bus 0
id 1 or id of drive
lun [default] 0
Do you want to continue yes
2 use entire disk
q quit
1 scan entire disk or q to quit
scan [quick/destructive]
do you wish to make manual adjustments [yes]
n for name
0 for division
name [work2]
q quit
i install
mkdev fs
1 add filesystem
/dev/work2
work2
yes
[1] always mount
[yes] allow users
mountall
```