

INSTALLING 2ND HARDDRIVE

8-27-01

mkdev hd [enter]

Pick # 2 add scsi hard drive

host adapter [default] ad or alad blad

host adapter 0

bus 0

id 1 or id of drive

lun [default] 0

update scsi configuration **yes**

relink kernel at this time only if there are no more hd's to configure

to add another hd answer no and make mkdev hd again.

If finished answer **yes** .

Boot by default **yes**

Environment to be rebuilt **yes**

Reboot and start mkdev hd again

MKDEV HD [enter]

Pick # 2 add scsi hard drive

host adapter [default] ad or alad blad

host adapter 0

bus 0

id 1 or id of drive

lun [default] 0

Do you want to continue **yes**

2 use entire disk

q quit

1 scan entire disk or q to quit

scan [quick/destructive]

do you wish to make manual adjustments **[yes]**

n for name

0 for division

name [work2]

q quit

i install

mkdev fs

1 add filesystem

/dev/work2

work2

yes

[1] always mount

[yes] allow users

mountall