

## Setup of Wyse Terminal, Oki Printer, and Modem

If your terminal is a Wyse 150, then follow these instructions:

- a. First, Enter into the setup menu by depressing the Shift (bottom left keyboard)/ and the Select Key
- b. Hit the F-2 Key**
- c. Change the Personality= to Wyse 150
- d. Change the Scrl= to Jump
- e. Change the Rcv Cr= to CRLF
- f. Hit the F-4 Key**
- g. Change the Baud Rate= to 19200
- h. Change the Rcv Handshake=to Xon-Xoff/XPC
- i. Comm= to FDX
- j. Xmt Lmt= to 150 cps
- k. Hit the F-11 Key**
- l. Change the Printer=to Parallel
- m. Hit the F-12 Key** Spacebar to Yes, and Hit the F-12 key to Save and Exit